

**BRIAN WOOD**Executive Building Consultant
Dental Loss Consultant brian.wood@rmcteam.com
newloss@rmcteam.com M (913) 277-7187
O (913) 601-4546 Lincoln, NE[SUBMIT ASSIGNMENT](#)

Areas of Expertise

Health Care Consulting - Residential Reconstruction - Commercial Reconstruction

EXPERIENCE

Brian Wood is a Senior Building Consultant with extensive experience managing complex property losses across commercial, healthcare, residential, and institutional sectors. His expertise spans catastrophe response, damage assessment, scope development, and project oversight, with a strong focus on minimizing business interruption and ensuring regulatory compliance. Brian has led teams of consultants, engineers, and hygienists through high-stakes restoration efforts, including tornadoes, hurricanes, hailstorms, and fire events, consistently delivering accurate estimates and coordinated recovery plans.

Throughout his career, Brian has consulted on multi-million-dollar losses involving dental offices, apartment complexes, banks, senior living facilities, and medical imaging equipment. He has worked closely with carriers, contractors, and municipal authorities to manage emergency repairs, abatement and debris removal budgets, and construction timelines. His leadership in CAT events such as Hurricane Florence and the Temple, TX tornado demonstrates his ability to mobilize large teams, conduct hazmat testing, and produce detailed rebuild estimates—all while maintaining safety standards and scope alignment. Brian's hands-on approach and technical precision make him a trusted advisor in both emergency response and long-term recovery.

RELEVANT EXPERIENCE

- RMC Group, Executive Building Consultant
2024 to Present
- RMC Group, Senior Building Consultant
2021 to 2024
- RMC Group, Building Consultant
2017 to 2021
- Firefighter & Head of Building Inspections, Lincoln NE
1997 to 2018
- Nebraska Air National Guard
1996 to 2018

FEATURED PROJECTS

- **Hail, Aurora, CO - 2024**
Brian served as the lead consultant for a hailstorm event that impacted the exterior of 75 apartment buildings across two complexes. He managed a coordinated team of five to perform detailed inspections, scope development, and contractor bid analysis. Acting as the liaison between project teams and insurance carrier clients, Brian ensured scope alignment and adherence to mitigation budgets, construction cost constraints, and business interruption protocols all within set budget thresholds. His expert budgeting/oversight and facilitation of abatement/debris removal timelines supported a seamless resolution of the loss, valued at \$2.2M and \$2.3M respectively.
- **Lightning, Middleton, CO - 2019**
The damage assessment and restoration planning for a neurological facility were overseen by Brian after a lightning-induced power surge disabled a \$1M CT scanner. He collaborated alongside engineer crews, hygienist teams, and specialized mitigation contractors to coordinate emergency repair and building preservation. His scope included expert budgeting/oversight, evaluation of drying objectives, and adherence to mitigation plans and construction cost constraints. Acting as the liaison between project teams and insurance carrier clients, Brian ensured scope alignment and managed abatement/debris removal budgets and timelines, all within set NTE thresholds. His leadership helped restore critical healthcare operations with minimal disruption.
- **Dental Office - San Diego, CA - 2019**
Brian served as the lead consultant for a dental office loss involving significant equipment damage and business interruption. He collaborated alongside engineer crews, hygienists, and mitigation contractors to coordinate emergency repair and building preservation efforts. His scope included relocation services to maintain patient continuity, expert budgeting/oversight, and adherence to mitigation plans and construction cost constraints. Acting as the liaison between project teams and insurance carrier clients, Brian ensured scope alignment and managed abatement/debris removal budgets and timelines supporting an estimated rebuild and healthcare compliance at 1M+.

BRIAN WOOD

Executive Building Consultant
Dental Loss Consultant



FEATURED PROJECTS CONTINUED

- **Hurricane Florence, Jacksonville, NC - 2018**
Responding to a catastrophe, Brian consulted on a roof collapse at a bank in Jacksonville, NC, caused by damages incurred following Hurricane Florence. The total value of the loss was substantial, involving teams of consultants, vendors, and general contractors to address the extensive damage to the building with its detailed technical security systems and physical limitations of the bank building. Beyond estimating the loss and reporting, Brian played a crucial role in keeping within set NTE thresholds for all emergency repair and building preservation, expert budgeting/oversight, onsite 24-hour security, as well as customer service and business disruption management.
- **Hurricane Florence, Various locations, NC - 2018**
Brian was part of a large-scale CAT team stationed in North Carolina with critical response to several water and wind losses throughout the affected hurricane zone. Responsible for overseeing emergency repair and building preservation, Brian also managed a team of over 25 consultants, hygienists, and engineers to perform hazmat testing and demolition, while contiguously writing rebuild estimates. Concentrating on mitigation plans, construction cost constraints, and business disruption management, mindful of set NTE thresholds, he addressed safety and environmental concerns, working closely with abatement experts and the hygienist team to manage abatement/debris removal budgets and timelines.
- **Hail, Idaho Falls, ID - 2018**
Inspecting each individual building, Brian consulted on a massive hail project for a large retirement center with damage to multiple buildings. The hailstorm caused significant damage, necessitating emergency repair and building preservation, expert budgeting/oversight, as well as healthcare, patient, and business interruption management. Brian supervised various teams of consultants, architects, with environmental specialists while managing clearance/waste removal schedules and keeping in compliance with recovery strategies and budgetary limitations with an agreed scope valued around \$650K.
- **Water, Attleboro, MA - 2018**
Consulted on a significant water loss at a dental office caused by a plumbing failure, Brian managed damages estimated at \$1M. He collaborated alongside consultants, engineers, and environmental specialists to coordinate emergency repair and building preservation, manage abatement and debris removal budgets, and ensure scope alignment with mitigation plans and construction cost constraints. The incident was managed with keen oversight which prevented disruption of daily operations considering relocation protocols, underscoring the urgency and compassion Brian brought to restoring continuity in a healthcare setting.
- **Flood, Madison, WI - 2018**
Brian responded with a team ready for a major flood event that severely impacted a dental office's infrastructure and equipment, requiring immediate intervention to preserve operations. He worked closely with consultants, engineers, and dental hygienists to organize urgent repairs and safeguard the facility, oversee abatement and debris removal costs, and ensure alignment with mitigation strategies and construction budget limits and thresholds. Recognizing the urgency of maintaining patient care, Brian facilitated the relocation of the practice to a temporary facility, helping the staff continue serving patients without interruption.